CRITICAL ITEMS LIST (CIL)

SYSTEM:

SUBSYSTEM:

Electrical

LHZ Aft Feedthru Receptacle

FUNCTIONAL CRIT: PHASE(S):

1R

REV & DATE: DCN & DATE:

J, 12-19-97

HAZARD REF:

E.01

ANALYSTS:

J. Bowski/A. Oser

FAILURE MODE:

Fails Shorted

FAILURE EFFECT:

Loss of mission and vehicle/crew due to engine(s) being destroyed. b)

TIME TO EFFECT:

Seconds

FAILURE CAUSE(S):

Faulty Contact

REDUNDANCY SCREENS:

Screen B: FAIL - Not detectable in flight.

Screen C: PASS

FUNCTIONAL DESCRIPTION: The cryogenic feedthru connector provides the electrical connection between the level

sensors in the LH2 tank and the external harnesses.

EFFECTIVITY FMEA ITEM PART NO. PART NAME OTY CODE(S) 3.11.7.2 1 LWT-54 & Up 81L2-2 Feedthru Receptacle (302A02 J1, J2)

REMARKS:

CRITICAL ITEMS LIST (CIL) CONTINUATION SHEET

SYSTEM: SUBSYSTEM: Electrical

LH2 Aft Feedthru Receptacle

REV & DATE: DCN & DATE: J, 12-19-97

FMEA ITEM CODE(S):

3.11.7.2

RATIONALE FOR RETENTION

DESIGN:

The cryogenic feedthru receptacle is a jam nut mount. It is designed with a shell made from CRES 304 or 304L per QQ-S-763. The jam nut is CRES 321 or 304L per QQ-S-763. The shell and nut are cadmium plated per QQ-P-416. The insert is virgin teflon per MIL-P-19468. The hermetic sealing is accomplished by the use of a fused glass insert of a vitreous material. The pin contacts are constructed of iron-nickel alloy per MIL-I-23011 and are gold plated per MIL-G-45204. This connector is designed to meet the dielectric requirements of 1000V RMS at 60 Hz and 5000 megohms insulation resistance.

The fusing of the glass insert provides for setting of the contacts in required position. The location and contact set up is per Lockheed Martin Standard Drawing 81LZ.

Redundancy Description

Since each depletion sensor has its own pins on the feedthru connector, the redundancy description and effects of loss of redundancy for the fails short failure mode are the same as described for the fails wet mode of the depletion sensors. Circuits are routed on non-adjacent pins on the connectors to reduce the probability of one failed circuit affecting another.

Effect of First Failure

If any one circuit fails so as to produce a false wet indication, there is no effect since there are three circuits remaining.

Effect of First Redundancy Loss

If a second circuit fails so as to produce a false wet indication, there is no effect since there are two circuits remaining.

Effect of Second Redundancy Loss

If a third circuit fails so as to produce a false wet indication, the depletion function will be lost and the effect described above will occur.

TEST:

The Feedthru Receptacle is qualified. Reference COO MMC-ET-TMO6-116.

<u>Vendor:</u>

Perform Dielectric Strength Test (Standard Drawing 81L2).

Perform Insulation Resistance Test (Standard Drawing 81L2).

CRITICAL ITEMS LIST (CIL) CONTINUATION SHEET

SYSTEM:

Electrical

SUBSYSTEM:

LH2 Aft Feedthru Receptacle 3.11.7.2

REV & DATE: DCN & DATE:

J, 12-19-97

FMEA ITEM CODE(S):

RATIONALE FOR RETENTION

TEST: (cont)

MAF:

Perform System Isolation Resistance Test (TMO4k).

Launch Site:

Perform System Resistance Test (QMRSD File IV).

Perform System Functional Test (OMRSD FILE II).

INSPECTION:

Lockheed Martin Procurement Quality Representative:

Witness Dielectric Strength Test (Standard Drawing 81L2).

Witness Insulation Resistance Test (Standard Drawing 81L2).

MAF Quality Inspection:

Inspect connector and pins for freedom of damage, are not broken, bent, misaligned or corroded, and connector is free of foreign material (STP6501).

Witness Isolation Resistance Test (TMO4k).

Launch Site:

Witness System Resistance Test (OMRSD File IV).

Witness System Functional Test (OMRSD File II).

FAILURE HISTORY:

Current data on test failures, unexplained anomalies and other failures experienced during ground processing activity can be found in the PRACA data base.